

Clippard
 INSTRUMENT LABORATORY, Inc.
 Cincinnati, Ohio 45239
Minimatic®
 U.S. PAT. NO'S 3,766,935; 3,766,831 PAT'S PEND.

MADE IN U.S.A.

Pressure Reg. **R701**

Clippard
 INSTRUMENT LABORATORY, Inc.
 Cincinnati, Ohio 45239
Minimatic®
 U.S. PAT. NO'S 3,766,935; 3,766,831 PAT'S PEND.

MADE IN U.S.A.

Flow Control **R501**

- WARNING -
 FOR CONTINUED PROTECTION
 AGAINST FIRE HAZARD, REPLACE
 FUSES WITH SAME TYPE AND
 RATING ONLY.

3AG 10A 250V PB
 3AG 10A 32V MB
 3AG 10A 32V MB
 3AG 15A 32V MB

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

CAUTION-HOT
 ALLOW TO COOL
 BEFORE REMOVAL
 HANDLE CAREFULLY-
 DELICATE LAMP FILAMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

MOTOR-SYNCHRONOUS (DM)
 CONTINUOUS DUTY THERMAL PROTECTED
 1/35 H.P., 1 PH., 115V.A.C., 50/60 HZ
 1500/1800 R.P.M. .75/.65 AMPS
 CAP. 5 MFD 370 VAC
 INSULATION CLASS B
 PART NO. 252193

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT



DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT



FILLER PLUG & AIR VENT
 ABOVE 20°F. USE OIL.
 SPEC. MIL-H-5606
 BELOW 20°F. USE OIL SPEC.
 MIL-H-5606 MIXED WITH 26%
 NAPHTHA SPEC TT-N-95
**CAUTION CLOSE AIR VENT
 WHEN NOT IN USE**

WARNING
 FOR-043 ANGLE GEARBOX ASSYS
 USE ONLY HYDRAULIC PUMPS
 THAT HAVE "O" RING TYPE
 GREASE RETENTION SPLINES
 (67WAF200 PUMP OR EQUIVALENT)

SS9013-1167



DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

⊠ **INTENSIFY** ⊠
 ⊠ **ACTIVATE** ⊠
 SLO-BLO
 ⊠ **INTENSIFY** ⊠
 ⊠ **ACTIVATE** ⊠
 SLO-BLO



DANGER
 HIGH VOLTAGE 1KV
 ELECTRIC SHOCK HAZARD
 REMOVE POWER BEFORE
 REPAIR OR ADJUSTMENT

